

## **Plant Hazard Analysis & Risk Assessment**

Monitor
ABN: 76 159 267 679
143 Gunnedah Rd
Tamworth NSW 2340
Ph: 02 6755 6000
E: service@monitor.net.au

**Model:** Forst ST8 Date: 03/09/2024



## Person conducting assessment:

This Hazard Identification and Risk Assessment document is Model specific. It is based on the knowledge that all new machines of this model were/are produced to the same specification and design. It assumes all examples of this exact model currently in service to be as per the original specification, and to have been and continue to be operated and maintained in accordance with the Manufacturers requirements, and with all applicable statutory and regulatory requirements of an original example of the Model for which it was prepared. This Assessment must be reviewed by all stakeholders as required:

- Having regard to the manufacturers approved options
- Having regard to the general arrangement of miscellaneous equipment or facilities that may be provided on the plant according to the end users requirements or specification
- According to the particular circumstances under which the plant is used and maintained
- As new Hazards are identified and/or as risks are reassessed
- As existing risk control measures are revised or new risk control measures are introduced and implemented
- As and when work procedures are altered or revised
- Having regard to any unauthorised alterations or modifications made to the design or operation of the equipment

Monitor have made every attempt to identify all reasonably foreseeable operating circumstances in preparing this Assessment, however no guarantee as to the completeness of this Assessment is provided or implied. It is the responsibility of Owners, Employers and Operators to identify all hazards associated with the use of this equipment specifically applicable to the task to be carried out and to where the equipment is to be used or located. They must assess the risk potential for each of the identified hazards and ensure that all reasonably practicable steps are taken to ensure those risks are effectively controlled.

- All operators must be trained and competent in the safe use of this particular piece of equipment, and hold appropriate qualifications as required by applicable regulatory requirements
- Operators of the equipment to which this Plant Risk Assessment refers must read and understand the Instructions for Use and Warnings contained within the Operators Manual prior to use
- All Daily Pre-Start Checks, Routine and Periodic Inspections, Maintenance and Repairs to this equipment must be carried out in accordance with the requirements of AS2550.10-2006

Revision:

ID	Description of Hazard Potential		Activity	Risk control measures already	Risk	Supplementary risk control	Risk
	Origin	Consequence		implemented		measures	score
1	Operator Competency						
1.1	Untrained operator, not following proper operating procedures.  Distracted operator.  Following a poor system of work.  Operator working alone.	Entanglement (amputation/death) Laceration / cuts / bruises / fractures Serious injury or death	Set up Operation Maintenance	Operation instructions explained in operator's manual	C4 Extreme	Train operators on safe use of the plant.  Operator training should include at least the following:  • pre-operation inspections  • safe operation of plant  • regular maintenance tasks  • understanding of plant operation  • capabilities and limitations  • emergency procedures  Do not operate the plant unless proper training has been received.  Ensure operator's manual is kept with the plant for reference.  Do not operate the plant when distracted, ill, excessively fatigued, or under the influence of drugs or alcohol.  Implement appropriate system of work based on manufacturer's recommendations (e.g. operating instructions shown in operator's manual).	B1 Low
1.2	Misuse Unauthorised use of plant	Entanglement (amputation/death) Laceration / cuts / bruises / fractures Serious injury or death	Operation	Operator's manual warns about not using the plant for other than its intended purpose.	C4 Extreme	Do not use the plant for any other purpose than its intended use as explained in the operator's manual.  Do not operate the plant unless proper training has been received.	C4 Extreme

© Monitor 2023

Document Number: 01

**Date:** 03 Sep. 2024

Revision: 01

THIS DOCUMENT IS CONTROLLED – UNCONTROLLED WHEN PRINTED

ID	Description of	Description of Hazard Potential		Risk control measures already	Risk	Supplementary risk control	Risk
	Origin	Consequence		implemented		measures	score
						Keys are not to remain in an unattended machine.	
2	Plant Limitations						
2.1	Excessive incline causing plant to overturn	Roll over	Driving Operation	Operator's manual recommends that you do not drive on ground with an incline in excess of 20°.	C3 High	Do not drive the plant over ground slopes which exceeds its limitations.  Avoid driving on ground too soft to support the machine's weight.  Make sure the engine and hydraulic oil are warm before working on inclined ground.  If the machine has to be stopped on an incline, make sure that the machine is pointing either up or down the slope. Also chock both wheels at the downhill end.	B2 Low
3	Operation						
3.1	Damaged control panel	Crushing Impact	Set up Operation		C2 Medium	Regularly inspect control panel.	A1 Rare
3.2	Moving chipper into position	Overturning Crushing	Driving Set up	Follow maximum inclination limits set by manufacturer. Found in operator's manual.	C4 Extreme	Carry out job site risk assessment to determine suitability of the site before commencing any work.  Avoid driving on steep ground; find alternative routes whenever possible.  Do not drive at fast speeds.  Avoid harsh use of the levers as both levers used in extreme opposition will cause the machine to spin on its axis.  Avoid driving on ground too soft to support the machine's weight.	B2 Low

Authorised By: © Monitor 2023

Title:

Plant Risk Assessment Managing Director Document Number: 01

**Date:** 03 Sep. 2024

Revision: 01

THIS DOCUMENT IS CONTROLLED – UNCONTROLLED WHEN PRINTED

ID	Description of Hazard Potential		Activity	Risk control measures already	Risk	Supplementary risk control	Risk
	Origin	Consequence		implemented		measures	score
						Do not stand on the lower side of the plant while driving on steep ground.  Never drive across steep ground,	
						always drive with the wheels parallel to ground inclination.	
3.3	Set up	Struck by flying debris – sticks, branches, timber	Operation	Operator's manual states when in use, woodchip and debris are ejected with considerable force from the chute and can travel up to 10m.	D3 High	Ensure only operators are within work area - ensure the exclusion zone is in place and operational.  Do not allow discharge to be directed onto roads or public rights of way.  Make sure the chute directs woodchip to a safe location so that no one can be harmed or property damaged.	B2 Low
3.4	Prestart inspection	Laceration / cuts / bruises / fractures	Operation	Prestart inspection as per manufacturers recommendation. Chipper fitted with - E-Stop - Forward reverse buttons - Stop bar		Ensure any fitted safety devices or equipment are in good condition and functional during Pre-start check.	A1 Low
3.5	Uncontrolled movement of plant components	Entanglement (amputation/death) Laceration / cuts / bruises / fractures Serious injury or death Muscular stress / Musculoskeletal Disorder	Set up Operation Maintenance Cleaning Troubleshoot	Prestart inspection as per manufacturers recommendation. Feed and engine speed are controlled with a "No Stress" function ensuring that cutting conditions are kept within optimum limits. This maximises	C3 High	Isolate power to plant and remove the main switch key when performing maintenance and cleaning tasks.  Maintenance to be carried out by a competent person.  Pay attention to hazard decals to machine.	B2 Low

Title:
Authorised By:
© Monitor 2023

Plant Risk Assessment Managing Director **Document Number: 01** 

Page:

4

ID	Description of Hazard Potential		Activity	Risk control measures already	Risk	Supplementary risk control	Risk
-	Origin	Consequence		implemented		measures	score
				throughput while minimising jams and blockages. There will be times when material is being cut and the feed will momentarily stop until engine speed increases. At this point, the feed will start without warning.			
3.6	Operator safety	Entanglement (amputation/death) Laceration / cuts / bruises / fractures Serious injury or death	Set up Operation Maintenance Cleaning Troubleshoot	Ensure operator:  - Has no loose clothing or jewellery, hair tied back - Has snug fitting PPE with no cuffs or strings - Has clothing tucked in where applicable Is provided with correct rated hearing protection Safety footwear	D4 Extreme	May require dust mask dependant on type of timber being chipped.	B2 Low
3.7	Feeding material into chipper	Entanglement (amputation/death) Laceration / cuts / bruises / fractures Serious injury or death Muscular stress / Musculoskeletal Disorder	Operation	Operator's manual recommends that you do not try to force material over 203mm in diameter or 254mm wide into the machine.  Use speed (RPM) as directed by manufacturer. Do not exceed.	D4 Extreme	Ensure material to be chipped is clear of metal, stones, plastic, fauna, pests, diseases, rope or other contamination.  Ensure material of suitable size for chipper. De-limb/cut as required.  Load materials from side of in-feed chute.  Do not stand in front during loading.	B3 Medium

Plant Risk Assessment Title: Authorised By: Managing Director

© Monitor 2023

Revision: 01

**Date:** 03 Sep. 2024

Page:

**Document Number: 01** 

ID	Description of Hazard Potential		Activity	Risk control measures already	Risk	Supplementary risk control	Risk
	Origin	Consequence		implemented		measures	score
						Place butt-end first. Push short stubs through with longer branches.	
						Lay shorter branches of top of longer ones.	
						Do not place hands or body parts into in-feed chute.	
						Once in-feed grabs material, step back from chipper. Do not use force to push materials through.	
3.8	Discharge	Struck by flying debris – sticks, branches, timber	Operation	Follow procedure in operator's manual if blockage occurs.	D4 Extreme	Ensure discharge chute pointed downwards (reduce dust).	B2 Low
		Entanglement				Clear away discharge regularly.	
		(amputation/death) Laceration / cuts / bruises / fractures-				If chipper begins to vibrate or shake violently, stop work immediately and stop machine.	
		Serious injury or death				Always stop machine, wait for moving parts to stop and lock out power to chipper before removing any blockages.	
						NEVER climb or stand on chipper/in-feed.	
3.9	Faulty/out of order, or poorly maintained plant	Entanglement (amputation/death) Laceration / cuts / bruises / fractures	Operation Emergency Maintenance	Operator's manual outlines plant maintenance schedule. Current maintenance	B4 High	Always perform pre-operation inspection before operating the plant.	B1 Low
		Serious injury or death		inspections up to date as per manufacturers		Implement 'tag out' procedure to isolate faulty/out of order plants.	
		Muscular stress / Musculoskeletal		recommendation.		Do not use an 'out of order' plant.	
		Disorder				Record all faults in logbook.	
						Perform plant maintenance as per	

© Monitor 2023

Document Number: 01

**Date:** 03 Sep. 2024

Revision: 01

THIS DOCUMENT IS CONTROLLED – UNCONTROLLED WHEN PRINTED

ID	Description of Hazard Potential		Activity	•		Supplementary risk control	Risk
	Origin	Consequence		implemented		measures	score
						manufacturer's maintenance schedule.	
						Keep maintenance records / plant logbook up to date.	
3.10	Refuelling	Explosion Fire			B4 High	When refuelling:  • Keep away from ignition sources;  • Do not smoke;  • Avoid spilling fuel over hot engine.	A2 Low
3.11	Engine exhaust pipe	Burn	Operation	Exhaust pipe guarded.	C2	Do not touch exhaust pipe when	A1
				"Hot surface" decal in place.	Medium	hot.	Low
3.12	Plant modifications after completion of risk	Crushing Overturning	Operation Set up		C5 Extreme	Ensure modifications made to the plant are inspected, assessed, and approved by a competent person.	B1 Low
	assessment.					Review hazard analysis and risk assessment after plant modifications.	
4	Transport / Handling						
4.1	Unsecured vehicle	Impact	Transport		C4 Extreme	Ensure the machine is secured in accordance with the requirements described in the manual and with relevant transport regulations.	A2 Low
4.2	Injury sustained	Strains / Sprains	Transport	Trailer is fitted with park brake	C3	Ensure park brake is applied	A2
	when hitching to or unhitching machine	Crush Impact		and safety chain. Jockey wheel fitted to lift machine to	High	before unhitching from vehicle.	Low
	from towing vehicle	ппрасс		tow coupling height.		Ensure jockey wheel and tow coupling are maintained or	
						replaced if damaged.	

© Monitor 2023

Document Number: 01

**Date:** 03 Sep. 2024

Revision: 01

THIS DOCUMENT IS CONTROLLED – UNCONTROLLED WHEN PRINTED

ID	Description of Hazard Potential		Activity	Risk control measures already	Risk	Supplementary risk control	Risk
	Origin	Consequence		implemented		measures	score
4.3	Towing Machine	Overturning Impact	Transport		C3 High	Ensure machine is in transportation mode before departing:	A2 Low
						<ul> <li>Hopper tray is secured in the up position</li> <li>Discharge chute is securely fixed at the inboard position</li> <li>Rear support stand up.</li> </ul>	
						Clear machine of loose woodchip material before departing.	
4.4	Incorrect replacement tyre fitted	Crushing Overturning Impacting	Operation	Maintain correct tyre inflation pressures as per manufacturers recommendation.	B4 High	Ensure replacement tyres match the plant manufacturer specifications.	A1 Low
4.5	Flat tyre	Overturning Crushing Impact	Operation	Prestart inspection as per manufacturers recommendation.	C4 Extreme	Regularly check condition of pneumatic tyres.  Avoid driving over sharp obstacles or debris.	B1 Low
4.6	Lifting	Crush Impact	Transport Lifting	Lifting procedure included in Operator's Manual.  Data plate on machine and specifications in Operators Manual show the machine gross weight.  Machine fitted with a lifting eye.	C5 Extreme	Follow appropriate lifting procedure.  The lifting eye can only support the weight of the woodchipper.	B2 Low
5	Plant Failure						
5.1	Power Failure Burst hydraulic hose	Crushing Overturning	Set up Operation		A3 Medium	Check hydraulic hose condition during periodic maintenance.	A2 Low
		Burn Skin irritation	Maintenance			Report and "tag out of service" if identified.	

© Monitor 2023

Document Number: 01

**Date:** 03 Sep. 2024

Page:

Revision: 01

ID	Origin Consequence		implemented		Risk	Supplementary risk control	Risk
						measures	score
5.2	Excessive hydraulic	Impact	Set up		C3	Check pressure settings during	A1
	oil pressure.	Crushing	Operation		High	preventative maintenance.	Low
5.3	Emergency Stop not	Crushing	Emergency		C4	Check that the emergency stop	B1
	available	Impact	Maintenance		Extreme	button functions correctly.	Low
		Trauma					
5.4	Inadequate	Crushing	Maintenance	Maintenance procedures	C3	Allow only qualified service	A2
	maintenance	Impact		included in Operator's Manual.	High	personnel to perform	Low
	procedures					maintenance tasks.	

Plant Risk Assessment Title: Authorised By:

Managing Director

**Date:** 03 Sep. 2024

Revision: 01

© Monitor 2023

THIS DOCUMENT IS CONTROLLED – UNCONTROLLED WHEN PRINTED

**Document Number: 01** 

RISK	MATRIX			ACTION	HEIRACHY OF CONTROLS				
				CONSEQUENCE			until further control measures are implemented to lower the risk. Senior management attention required.  HIGH – Review and introduce additional controls to lower level of risk. Needs senior management attention.  MEDIUM – Monitor and maintain supervision and controls. Specify management responsibility.  the source  Substitution – e.g. is substance or activity hazardous one  Isolation – e.g. use isolate the hazard, machinery, installing machinery  Engineering – e.g. of equipment to counter the source  Administration – p.g. of the source  Substitution – e.g. is substance or activity hazardous one  Alexander of the source  Substitution – e.g. is substance or activity hazardous one  Substitution – e.g. is substance or activity hazardous one  Additional controls to lower level of risk. Needs senior machinery  Administration – p.g. of the source  Control of the source  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Additional control of the hazard, machinery is substance or activity hazardous one  Administration – p.g. of the hazard, machinery is substance or activity hazard	Elimination – controlling the hazard at	
		1. Insignificant	2. Minor	3. Moderate	4. Major	5. Catastrophic		are implemented to lower the 2. Substit	2. Substitution – e.g. replacing one
	E. Almost Certain Is expected to occur immediately or within a short timeframe	HIGH	HIGH	EXTREME	EXTREME	EXTREME		hazardous one 3. Isolation – e.g. use of barriers to shield or isolate the hazard, enclosures for noisy	
۵	D. Likely Will probably occur in most circumstances	MEDIUM	HIGH	HIGH	EXTREME	EXTREME		level of risk. Needs senior management attention.  MEDIUM – Monitor and maintain supervision and controls. Specify management responsibility.  machinery  4. Engineering – e.g. design and equipment to counteract the  5. Administration – policies and for safe work practices  6. Personal Protective Equipme respirators, ear plugs, face m	4. Engineering – e.g. design and install
ПКЕПНООБ	C. Possible Could happen and has occurred here or elsewhere	LOW	MEDIUM	HIGH	EXTREME	EXTREME			
=	B. Unlikely Unlikely to occur	LOW	LOW	MEDIUM	HIGH	EXTREME			<ol> <li>Personal Protective Equipment – e.g.     respirators, ear plugs, face masks, safety     glasses, safety shoes</li> </ol>
	A. Rare Not expected to occur	LOW	LOW	MEDIUM	HIGH	нібн	LOW – Monitor and manage by routine procedures and monitoring.	Glasses, surery shoes	

CONSEQUENCE	DESCRIPTORS		
SEVERITY	SAFETY	ENVIRONMENT	BUSINESS
5. Catastrophic	Potential for incident resulting in serious damage and/or fatality	The aspect is legally or contract regulated and has the potential for a disastrous long term impact resulting in prosecution.	Loss > \$1M
4. Major	Potential for incident resulting in serious damage and/or permanent disabling illness or injury	The aspect is legally or contract regulated and has the potential for a serious long term impact resulting in prosecution.	Loss of service provision
3. Moderate	Potential for incident resulting in significant damage and/or temporary disabling illness or injury	Significant environmental aspect with short term impact resulting in improvement notice.	Loss \$100K - \$1M
2. Minor	Potential for incident resulting in moderate damage and/or requiring medical treatment.	The aspect is legally or contract regulated and has the potential for a moderate reversible short term impact resulting in an improvement notice.	Prolonged reduction in service provision or productivity
1. Insignificant	Potential for incident resulting in minor damage and/or injury requiring first aid treatment	The aspect is not legally or contract regulated and has the potential for a minor negligible impact.	Loss \$10K - \$100K

Title:Plant Risk AssessmentDocument Number: 01Revision:01Authorised By:Managing DirectorDate:03 Sep. 2024

© Monitor 2023 THIS DOCUMENT IS CONTROLLED – UNCONTROLLED WHEN PRINTED Page: 10